

AssetWise Mobile v 01-11-01 - Decimal Issues

From Bentley:

We've become aware of an issue with report uploads from mobile in version 01.11.01.

There is a new version of the mobile app available now: 01.12.01. Please make sure the inspectors update ASAP. The inspectors do not need to upload any active reports on mobile before the update.

After updating the app, they can still upload reports with the understanding that:

For ALL report approvals, the inspector(s) should verify the list of fields attached for corrupted data. There will need to be manual edits for now.

They can use the audit log to figure out what the correct value should be.

In the meantime, we're working on a fix. This is most likely a site configuration issue, so another mobile app release won't be needed.

NBI 10: Minimum Vertical Clearance

NBI 11: Kilometerpoint

NBI 32: Approach Roadway Width

NBI 39: Navigation Vertical Clearance

NBI 40: Navigation Horizontal Clearance

NBI 47: Horizontal Clearance

NBI 48: Maximum Span Length

NBI 49: Structure Length

NBI 50A: Curb or Sidewalk Width: Left Side

NBI 50B: Curb or Sidewalk Width: Right Side

NBI 51: Bridge Roadway Width, Curb-To-Curb

NBI 52: Deck Width, Out-To-Out

NBI 53: Minimum Vertical Clearance OVER Bridge Roadway

NBI 54B: Minimum Vertical Underclearance

NBI 55B: Minimum Lateral Underclearance on Right: Minimum Lateral Underclearance

NBI 56: Minimum Lateral Underclearance on Left

NBI 76: Length of Structure Improvement

NBI 116: Minimum Navigation Vertical Clearance, Vertical Lift Bridge

WaterLevel

HighWaterMark

Fill Height

Cell Height

Cell Width

Cell Length