




SAP BI 39 1	Posting
SAP 39 1	6N, 20W
SAP 39 1 M	6N,10E; 8N,10E
SAP 39 1 S	5N, 10E
SAP 39 2 M	5N,10E; 6N,10E; 7N,10E
SAP 39 2 S	6N,10E; 8N,10E
SAP 39 3	9N, 10E
SAP 39 3 M	7N,11E; 9N,20W
SAP 39 3 S	9N,10E; 5N,10E
SAP 39 4	5N, 10E
SAP 39 4 M	6N, 20W
SAP 39 4 S	Several
SAP 39 5 M	Several-bridge repair
SAP 39 5 S	Several
SAP 39 6 S	6N, 10E
SAP 39 7	8N, 20W
SAP 39 7 M	7N, 11E
SAP 39 7 S	9N, 20W
SAP 39 8 M	Stripe
SAP 39 8 S	Several
SAP 39 9	8N, 11E
SAP 39 9 S	8N, 11E
SAP 39 10	6N, 10E
SAP 39 10 M	8N, 20W
SAP 39 10 S	Several
SAP 39 11 M	6N, 10E
SAP 39 11 S	Several
SAP 39 12	6N, 10E
SAP 39 12 M	Several-overlay
SAP 39 12 S	Several
SAP 39 13	5N, 10E
SAP 39 13 M	5N,10E; 8N,21W
SAP 39 13 S	Several
SAP 39 14	6N, 20W
SAP 39 14 M	6N, 20W
SAP 39 14 S	Several
SAP 39 15	5N, 11E
SAP 39 15 M	6N, 20W
SAP 39 15 S	Several
SAP 39 16	6N, 20W
SAP 39 16 M	6N,10E; 7N,11E; 8N,20W; 6N,20W
SAP 39 16 S	Several
SAP 39 17 M	Plans not found-Dec 2025
SAP 39 17 S	Several
SAP 39 18	8N, 20W
SAP 39 18 S	Several
SAP 39 19	8N, 20W
SAP 39 19 S	Several
SAP 39 20	9N, 10E
SAP 39 21	5N, 11E
SAP 39 22	5N, 10E
SAP 39 23	9N, 12E
SAP 39 24	7N, 10E
SAP 39 25	9N, 10E
SAP 39 26	6N, 10E
SAP 39 28	8N, 20W
SAP 39 29	7N, 20W
SAP 39 30	6N, 10E
SAP 39 31	6N, 10E
SAP 39 32	7N, 10E
SAP 39 34	SeveralL-overlay
SAP 39 35	7N, 10E
SAP 39 36	7N, 20W
SAP 39 37	9N, 10E
SAP 39 38	5N, 11E
SAP 39 39	8N, 20W
SAP 39 40	7N, 11E
SAP 39 41	7N, 11E
SAP 39 42	6N, 10E
SAP 39 43	5N, 11E
SAP 39 44	9N, 10E
SAP 39 45	8N, 10E
SAP 39 46	5N, 10E
SAP 39 47	5N,10E; 6N,12E; 7N,10E; 8N,20W; 9N,11E
SAP 39 48	5N,11E; 6N,11E
SAP 39 49	7N, 10E
SAP 39 50	5N, 20W
SAP 39 51	7N,11E; 7N, 10E; 8N,10E

LSBP 39 1	7N,20W; 5N,10E; 8N,10E; 8N,20W
LSBP 39 2	5N, 10E
LSBP 39 3	8N,21W; 5N,10E
LSBP 39 4	5N,11E; 8N,10E
LSBP 39 5	8N,10E; 5N,11E; 6N,10E
LSBP 39 6	5N, 11E
LSBP 39 7	6N,10E; 7N,21W; 9N,11E
LSBP 39 11	5N, 11E
LSBP 39 13	5N, 10E
LSBP 39 14	7N, 11E
LSBP 39 15	6N,10E; 4N,11E
LSBP 39 16	7N, 10E
LSBP 39 17	5N, 11E
LSBP 39 18	6N, 11E
LSBP 39 20	6N, 10E
LSBP 39 21	ERBR
LSBP 39 22	5N,10E; 6N,10E
LSBP 39 23	5N, 11E
LSBP 39 24	5N,10E; 7N,10E

BR 0039 7 B	5N, 11E
BR 0039 8 B	9N, 10E
BR 0039 10 B	9N, 20W
BR 0039 11 B	8N, 11E
BR 0039 12 BO	5N,10E; 7N,20W; 9N,21W
BR 0039 13 BO	8N, 21W
BR 0039 14 B	6N,11E; 8N,11E
BR 0039 15 BO	6N,10E; 8N,10E
BR 0039 16 BO	7N,11E; 9N,20W; 5N,10E
BR 0039 19 B	8N, 20W
BR 0191 20 B	7N, 20W
BR 1203 3 B	5N, 10E
BR 1210 3 B	7N,20W; 7N,21W
DS 1206 1 B	5N, 10E
ER 0039 2 B	Plans not found-Dec 2025
ER 0039 3 B	Plans not found-Dec 2025
ER 0039 18 B	Debris
ER 0175 4 B	6N, 10E
ER 0189 3 B	Plans not found-Dec 2025
MS038 039 1 B	Plans not found-Dec 2025
MS038 039 1 BI	Plans not found-Dec 2025
RS 0174 3 B	7N, 10E
RS 0191 18 B	7N, 20W
RS 0264 3 B	9N, 10E
RS 0279 6 B	8N, 21W
RS 1209 2 B	7N, 21W
S 0189 1 B	6N, 10E
S 0189 2 B	6N, 10E
S 0190 1 B	7N, 10E
S 0191 2 B	6N, 20W
S 0191 4 B	7N, 20W
S 0196 3 B	6N, 11E
S 0196 6 B	6N, 11E
S 0196 7 B	6N, 11E
S 0264 1 B	8N, 10E
S 0279 1 B	9N, 20W
S 0279 2 B	8N, 20W
S 0279 3 B	8N, 20W
S 0279 4 B	8N, 20W
S 1203 2 B	Plans not found-Dec 2025
S 1205 1 B	5N, 10E
S 1210 1 B	7N, 20W
S 187 2 1	6N, 10E
S 265 2 1	8N, 10E
SR 0264 6 B	8N, 10E
SR 1209 1 B	7N, 11E
SRS 0039 4 B	Eng
STP 0174 4 B	7N, 10E
STP 0175 6 B	7N, 11E
STP 0191 19 B	7N, 20W
STPD 0279 8 B	8N, 21W
PMS SRS RS 000S 039 B	Stripe